

**DEPARTMENT OF TRANSPORTATION****DIVISION OF ENGINEERING SERVICES**

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-011313**Date Inspected:** 30-Nov-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:****CWI Present:****Yes No****Inspected CWI report:** **Yes No N/A****Rod Oven in Use:** **Yes No N/A****Electrode to specification:** **Yes No N/A****Weld Procedures Followed:** **Yes No N/A****Qualified Welders:** **Yes No N/A****Verified Joint Fit-up:** **Yes No N/A****Approved Drawings:** **Yes No N/A****Approved WPS:** **Yes No N/A****Delayed / Cancelled:** **Yes No N/A****Bridge No:** 34-0006**Component:** Deck Panel**Summary of Items Observed:**

Bridge No. 34-0006 Component: Deck Panels

Summary of Items Observed: On this day Caltrans OSM Quality Assurance (QA) Inspector Gary Richmond was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhen Hua Port Machinery Company (ZPMC) at Chang Xing Island in Shanghai, China. QA Inspector observed and/or found the following:

On this date QA Inspector Gary Richmond gathered information compiled by the PAUT inspectors, regarding testing and inspections performed on Lift 12 Deck Panels. This information was input into the master folders kept on the Caltrop "Team China" Z drive.

QA Inspector performed in-process inspections of repairs made on Lift 12 Deck Panels in Bay 9 and Outside Yard.

On this date QA Inspector Gary Richmond was given ZPMC NDT Inspection Notification Sheet, Document No. 004766. This QA Inspector performed required Magnetic Particle Testing (MT) of approximately 10% of the area previously tested and accepted by ZPMC Quality control personnel, on the following items listed for the OBG sub-assemblies in Outside Yard.

DP-3017-001: No Recordable Indications Observed. Green Tag # 009518.

DP-3027-001: No Recordable Indications Observed. Green Tag # 009517.

---

## WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

### Summary of Conversations:

No relevant conversations noted.

### Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Richmond,Gary
----------------------	---------------

Quality Assurance Inspector
-----------------------------

---

<b>Reviewed By:</b>	Carreon,Albert
---------------------	----------------

QA Reviewer
-------------